

Software Update 2014-1

Release Notes

Resolved/Informational Items

John Deere Mobile Weather Failing to Load – Resolved intermittent issue of John Deere Mobile Weather object pool failing to load on GreenStar™ Display. (North America, Australia)

Application Controller 1120 Icon – Application Controller 1120 icon on GreenStar™ Display now reflect activated software functionality (John Deere Mobile Weather or John Deere Harvest ID, Cotton) (North America, Australia)



Software Versions – Bold items have changed from previous releases and are included in the software bundle. Please utilize the [John Deere Custom Performance website](#) to view and/or update controllers not included with this software bundle.

| Version # | Description |
|-------------------|---|
| 3.22.1095 | GreenStar™ 3 2630 Display |
| 2.8.1033 | GreenStar™ 2 2600 Display |
| 2.11.1068 | GreenStar™ 2 1800 Display |
| GSD 1.97 B | Original GreenStar™ Display |
| ITC 1.90 S | StarFire™ 3000 Receiver |
| ITC 3.73 E | StarFire™ iTC Receiver |
| LCR 1.10 C | StarFire™ 300 Receiver |
| SF 7.70 B | StarFire™ Gen II Receiver |
| 03B10 | John Deere Mobile RTK Modem |
| 1.10A | Machine Communication Radio |
| TCM 1.09 A | TCM |
| 2.40 G | Application Controller 1100 (iGrade™, Active Implement Guidance) |
| 1.30 B | Application Controller 1120 (John Deere Mobile Weather, John Deere Harvest Identification, Cotton) |
| ATU 1.13 A | AutoTrac™ Universal (ATU) 100 |
| ATU 2.20 B | AutoTrac™ Universal (ATU) 200 |
| RG2 2.04 B | AutoTrac™ RowSense - Universal |
| CAT 1.11 B | AutoTrac™ Controller |
| GRC 3.42 E | GreenStar™ Rate Controller |
| GDC 2.10 Q | GreenStar™ Rate Controller Dry |
| HMCT 1.07 C | Harvest Monitor™ Cotton SCM |
| CMFS 2.07C | Cotton Mass Flow Sensor CMFS |
| SMON 1.73 A | Original Harvest Monitor™ SPFH |
| HMON 1.20 C | Harvest Monitor™ Combine with In-Tank Moisture |
| MST 7.01 B | Harvest Monitor™ Elevator Mount Moisture Board |
| AC2 11 | Original Air Cart |
| SMVR 1.01M | SeedStar™ Gen II |